

2020 Reserve Study & Maintenance Plan

Vintage Oaks Condominium

Vancouver, WA

Prepared By:

Regenesis Reserves

Report Issued Date:

October 16, 2019

Site Inspection Date:

No Site Inspection Completed



October 16, 2019

Adna Trnjanin adnat@kpsinc.net Phone (360) 695-1538

RE: Vintage Oaks Condominium

Enclosed is the completed Reserve Study which meets the requirements of RCW 64.34.382. I prepared this Reserve Study and I am a reserve study professional.

SPECIAL NOTE ON FUNDING RESERVES

In an effort to provide the best and most useful information to the board, our reserve study software offers customizable funding plans. That means if the board has a different funding plan in mind than the one we recommend, we can produce that plan.

There are many approaches to funding reserves but it is recommended that Full (100%) Funding be pursued because it is most likely to avoid special assessments and it shares costs fairly among all members along the 30-year time line. Due to fluctuating inflation rates, investment rates, component costs, starting balances and useful life adjustments, the Percent Funded level will fluctuate (sometimes dramatically) from year to year. The Funding Plan takes these factors into consideration, make adjustment to the Annual Contribution and charts a new course toward Full (100%) Funding.

Type of Reserve Study Performed

A Level III Reserve Study Update with No Site Inspection was performed for this report.

Reserve Account Starting Balance

Effective the start of the 2020 fiscal year, based on information provided by client, the Projected Starting Reserve Balance is **\$240,760** versus the Fully Funded/Ideal Starting Balance is **\$647,760**.

Percent Funded

This homeowner association is currently **37% Funded** (Actual Starting Balance divided by Ideal Starting Balance.) 0-35%=Weak; 36-70%=Fair; 71-100%=Strong

Recommended Funding Plan Summary

A contribution of \$89,000 is recommended for the 2020 Fiscal Year (See funding plan for future year recommendations). Following this Recommended Funding Plan will adjust the level of reserves to 100% funded in 29 years, then maintain 100% funded moving forward.

REGENESIS A RESERVES

Reserve Study Consultants Oregon | Washington

Information needed by the board to comply with RCW 64.34.308 (Budget disclosure requirements) is located within the Funding Plan Summary. If the board plans to implement an Annual Contribution amount different than what is recommended in the Funding Plan Summary, the board must provide Regenesis with that amount in order to generate a revised funding plan.

State of Washington Required Funding Plan Reports

Based on Washington requirements, there are two additional Funding Plans:

- 1. **Full Funding Plan** to achieve 100% funded reserves by the end of the 30 year study period. See Fully Funded at 30 Years worksheet.
- 2. **Baseline Funding Plan** to maintain the reserve balance above zero throughout the 30 year study period without special assessments. See Baseline Funding worksheet.

Special Assessments

Based on current information and assuming the board follows the Recommended Funding Plan, no special assessments should be required for the coming year to pay for reserve study related expenditures. The board has not informed me of any implemented or planned special assessments.

Reserve Study Disclosure Required by Washington Statute:

"This reserve study should be reviewed carefully. It may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require you to pay on demand as a special assessment your share of common expenses for the cost of major maintenance, repair, or replacement of a reserve component."

Interest Yield on Reserves

A **0.01% Yield** is projected based on the current rate of return on your invested reserves. One of the benefits of the reserve study is it provides information needed to improve reserves investment returns. Investing reserves in CDs of differing maturities like 1 year, 3 year and 5 year based on when liquid funds will be needed will improve the average yield. A 1.5% average yield is achievable in the current market. If this rate was used in the projections, **\$324,444** in Interest Income would result over the 30 year projection period versus **\$2,163** produced by the current yield. Bottom Line: Increased Interest Income will lower owner contributions.

Inflation Rate

2.11% inflation rate was used based on the most recent 15-year average published by www.inflationdata.com

Tax Rate. 30% was used based on using Federal Tax Form 1120H versus 1120 which carries a 15% tax rate. Form 1120 is more complicated than 1120H, requirements are more stringent and tax preparers charge more to complete it. However, if interest earnings are high enough, the additional preparation cost can be worth it. See your CPA for more information on tax filing options.



Washington Sales Tax

All component costs have sales tax built in.

Annual Review & Update Service. An annual review and update of the Reserve Study is required by statute and necessary for continued accuracy. A review and update provides a new 30-year projection with current inflation factor, investment rates and any known component cost changes. **Delivered with this report is a Three Year Price Guarantee Proposal that will save considerable money.**

It's been my pleasure to provide this valuable financial and maintenance planning information. I can be available by teleconference, for up to one hour, to review this reserve study, answer questions and make revisions that are indicated. Tuesday, Wednesday or Thursday are generally my best available days. Please contact me to arrange a meeting.

Regards,

Michael B. Stewart PRA PROFESSIONAL RESERVE ANALYST

Miller



Reserve Study Table of Contents

METHODOLOGY

Explains the purpose of the reserve study, how the information was gathered and the sources used.

LIMITATIONS & ASSUMPTIONS

Explains what a Reserve Study does and does not do.

WORKSHEET REPORT

Alphabetical listing of the reserve components by type, cost, year put in service, useful life and replacement year

FUNDING PLAN SUMMARY REPORT

- Percent Funded: Starting Balance divided by the Ideal Balance
- **Ideal Balance:** Each component is measured, assessed for useful and remaining useful life plus cost of repair or replacement. Based on this analysis, each component should have a certain amount of money set aside as of the year in question. The Ideal Balance is the sum of all these component amounts as adjusted by the inflation factor.
- Starting Balance: Reserve funds total at beginning of each fiscal year
- Annual Contribution: Funds needed to meet the reserve schedule
- Interest Income: Yield on invested reserve funds
- Tax Liability: Federal taxes owed on investment interest earned

ANNUAL EXPENDITURES REPORT

Chronological repair and replacement schedule

STARTING BALANCE FUNDS DISTRIBUTION

Allocates available funds to the components. If funds are insufficient to fully fund each component, funds are allocated to components that are scheduled to happen sooner.



Reserve Study Methodology

DEFINITION

Reserve Study Identifies the components which will require maintenance, repair or replacement in more than one and less than thirty years and the cost of repair or replacement of each at recommended intervals. Site inspections are based on visual observation and no invasive testing was done. Representative sampling is used where visual inspection is not possible.

RESERVE STUDY CRITERIA

- 1. Identify current reserve funds balance
- 2. Identify components to be included
- 3. Establish reasonable useful life of each component
- 4. Establish remaining useful life of each component
- 5. Estimate current replacement or repair cost of each component
- 6. Assemble data in Reserve Study
- 7. Generate Reserve Funding Plan.

FUNDING PLAN CRITERIA

The Funding Plan is based on the Cashflow Method and includes Percent Funded, Inflation Adjusted Ideal Balance, Starting Balance, Annual Contribution, Interest Income, Tax Liability and Inflation Adjusted Expenditures. Inflation is based on the most recent 15-year average as determined by www.inflationdata.com

SOURCES OF INFORMATION (as applicable):

Original plans and specifications

Original builders and developers

Contractors and vendors

Industry Professionals (engineers, architects, construction managers, etc.)

Board Members

General Members

Property Manager

Resident Manager

Cost Estimating Services

To remain accurate, the Reserve Study must be updated annually



Reserve Study Limitations & Assumptions

- 1. The Reserve Study is intended for the sole use of the Client and is not to be construed as a guarantee, warranty or an opinion on the advisability of purchase.
- 2. The information provided by the Reserve Study is effective for one year from the completion date of the report. An annual review and update of this Reserve Study is required to adjust known cost changes and to maintain accuracy.
- 3. Consultant's financial liability for errors and omissions is limited to the charge made to Client to perform the Reserve Study.
- 4. The scope of the Reserve Study is expressly limited to the components included.
- 5. The useful life estimates of the Reserve Study assume normal weather conditions and do not factor in damage by flood, wind, storm, earthquake or other insurable events. The useful life estimates assume proper construction, installation, design and regular and adequate preventive maintenance. Improper construction, installation, design or failure to maintain will lead to shortened useful lives.
- 6. The cost estimates of the Reserve Study are based in current pricing for similar installations and materials and/or based in actual costs paid by Client. Future costs are subject to change according to supply and demand, material costs, effects of inflation and other factors which are not under Consultant's control.
- 7. The conclusions of the Reserve Study do not involve invasive testing of the components and were arrived at by either visual inspection and/or information provided by Client.
- 8. The Reserve Study is not intended to address or discover construction defects, asbestos, mold, water intrusion or lead paint. Client agrees to indemnify, defend and hold Consultant harmless from all related claims.

| Item Description | # of Items | Unit | | Current Item Cost | Re | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|---|---------------|------------|-------|-------------------------|--------|-----------------------------|---------------|----------------|-----------------|--------------|--------------|
| Barkdust | 1 | Total | \$ | 5,900.00 | \$ | 6,024 | 2018 | 2 | 2020 | 1 | No |
| Comments: 2018: Installed barkdust at dogrun area by | Barkdusters | \$908 | | | | | | | | | |
| 2017: Completed by Barkdusters \$5,900 | | | | | | | | | | | |
| 2014: Completed by Landscape Manageme | ent \$3,800 | | | | | | | | | | |
| 2012: Completed \$5,356 | | | | | | | | | | | |
| Clubhouse-Air Conditioning Unit | 1 | Total | \$ | 5,500.00 | \$ | 5,616 | 2005 | 15 | 2020 | 1 | No |
| Clubhouse-Appliances | 1 | Total | \$ | 2,250.00 | \$ | 2,297 | 2005 | 15 | 2020 | 1 | No |
| Comments: Dishwasher \$500 | | | | | | | | | | | |
| Range 750 | | | | | | | | | | | |
| Microwave 250 | | | | | | | | | | | |
| Refrigerator 750 | | | | | | | | | | | |
| Clubhouse-Bathrooms-Renovation | 2 | Each | \$ | 1,500.00 | \$ | 3,400 | 2005 | 20 | 2025 | 6 | No |
| Clubhouse-Drinking Fountain | 1 | Total | \$ | 800.00 | \$ | 907 | 2005 | 20 | 2025 | 6 | No |
| Clubhouse-Exercise Equipment | 1 | Total | \$ | 3,300.00 | \$ | 3,587 | 2013 | 10 | 2023 | 4 | No |
| Comments: Cost assumes purchasing used equipment | as advised b | y board. | | | | | | | | | |
| Nautilus treadmill (2015-used) | \$80 | 0 | | | | | | | | | |
| Nautilus recumbent (2015-used) | 60 | 00 | | | | | | | | | |
| Nautilus elliptical NE3000 (2011) | 600 |) | | | | | | | | | |
| Nautilus treadmill NHR800 (2005) | 80 | 0 | | | | | | | | | |
| TV | 5 | 00 | | | | | | | | | |
| Clubhouse-Flooring-Carpet | 132 | Sq.Yd. | \$ | 38.00 | \$ | 5,122 | 2005 | 15 | 2020 | 1 | No |
| Clubhouse-Flooring-Tile | 163 | Sq.Ft. | \$ | 16.00 | \$ | 2,956 | 2005 | 20 | 2025 | 6 | No |
| Clubhouse-Furnace | 1 | Total | \$ | 7,500.00 | \$ | 7,658 | 2005 | 15 | 2020 | 1 | No |
| Clubhouse-Furniture | 1 | Total | \$ | 12,500.00 | \$ | 12,764 | 2005 | 15 | 2020 | 1 | No |
| Comments: Sofa, 2 end tables, coffee table, sofa table, | 2 arm chairs | s, kitchen | tabl | e with 4 cha | irs, 3 | lamps, 1 g | uest ch | air, two | o 4 piece ai | rt sets, | 2 |
| hanging art sculptures, 10 large framed art | pieces, 25 f | olding cha | airs, | 3 folding tak | oles, | 2 office cha | irs | | | | |
| Clubhouse-Hot Water Heater | 1 | Total | \$ | 900.00 | \$ | 919 | 2005 | 15 | 2020 | 1 | No |

8 of 25

| Item Description | - | of ems | Unit | | Current Item Cost | | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|---|----------------|-----------|----------|-------|-------------------------|-------|-----------------------------|---------------|----------------|-----------------|--------------|--------------|
| Clubhouse-Keyless Access System | : | 1 | Total | \$ | 2,900.00 | \$ | 3,573 | 2019 | 10 | 2029 | 10 | No |
| Comments: 2019: Installed at a cost of \$2,869 | | | | | | | | | | | | |
| Clubhouse-Lights | | 1 | Total | \$ | 2,450.00 | \$ | 2,777 | 2005 | 20 | 2025 | 6 | No |
| Comments: 6 ceiling fixtures @ \$150 | \$900 | | | | | | | | | | | |
| 8 ceiling can fixtures @ \$100 | 800 | | | | | | | | | | | |
| 3 fluorescent fixtures @ \$150 | 450 | | | | | | | | | | | |
| 2 bathroom fixtures @ \$150 | 300 | | | | | | | | | | | |
| Clubhouse-Office Equipment | | 1 | Total | \$ | 2,900.00 | \$ | 3,153 | 2018 | 5 | 2023 | 4 | No |
| Comments: 2015: Replaced 1 computer and m | nonitor | | | | | | | | | | | |
| 2012: Replaced 2 computers; 1 pr | inter \$2,900 | | | | | | | | | | | |
| Clubhouse-Paint-Interior | : | 1 | Total | \$ | 3,500.00 | \$ | 4,051 | 2012 | 14 | 2026 | 7 | No |
| Comments: 2012: Completed in house. | | | | | | | | | | | | |
| Clubhouse-Security Camera | | 1 | Total | \$ | 2,100.00 | \$ | 2,588 | 2019 | 10 | 2029 | 10 | No |
| Comments: 2019: Installed at a cost of \$2,046 | | | | | | | | | | | | |
| Clubhouse-Window Treatments | | 1 | Total | \$ | 450.00 | \$ | 510 | 2005 | 20 | 2025 | 6 | No |
| Comments: Wood blinds on two windows. | | | | | | | | | | | | |
| Concrete Safety Repair | | 1 | Total | \$ | 3,000.00 | \$ | 3,194 | 2017 | 5 | 2022 | 3 | No |
| Comments: Inspect all walkways for tripping h 2016: Observed trip hazard north | | | remove | and | replace sele | ected | d areas as n | eeded. | | | | |
| Construction Defect Repair-Phase 1 | ; | 3 | Bldg. | \$ | - | \$ | - | 2017 | 50 | 2067 | 48 | Yes |
| Comments: Board advised construction defect Work will include new exterior pa | • | omplete | d at a r | ate c | of 3/year (\$4 | 100,0 | 000) startin | g in 201 | 17 and (| completed | by 201 | 9. |
| Dumpster Enclosures-Clean & Repair | | 5 | Each | \$ | - | \$ | - | 2016 | 50 | 2066 | 47 | No |
| Comments: Cleaned yearly and paid from Ope | erating Budget | | | | | | | | | | | |
| Fence-Perimeter-Chainlink-Vinyl-6' | 4,9 | 991 | Ln.Ft. | \$ | 22.00 | \$ | 153,357 | 2005 | 30 | 2035 | 16 | No |
| Garage Door-Maintenance | | 1 | Total | \$ | 750.00 | \$ | 850 | 2005 | 20 | 2025 | 6 | No |

9 of 25

| Item Description | # of Items | Unit | | Current Item Cost | | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|--|---------------|-----------|--------|-------------------------|-------|-----------------------------|---------------|----------------|-----------------|--------------|--------------|
| Gate-Access System-Loops | 1 | Total | \$ | 3,000.00 | \$ | 3,063 | 2005 | 15 | 2020 | 1 | No |
| Comments: 2013: Cost (\$2,644) and useful life (15 yea (7) total | ırs) provided | by Metro | Acc | ess | | | | | | | |
| Gate-Entry Access System | 1 | Total | \$ | 3,800.00 | \$ | 3,880 | 2005 | 15 | 2020 | 1 | No |
| Comments: Cost and useful life provided by Metro Ov Replace Elite ICON-26 when fails. Installed | | curity Ac | cess (| Control, Ph ! | 503.5 | 595.4716. | | | | | |
| Gate-Sensors | 1 | Total | \$ | 2,000.00 | \$ | 2,042 | 2010 | 10 | 2020 | 1 | No |
| Comments: Originally scheduled for completion in 20: 2013: Useful life of 10 years provided by N | | | | | | | | | | | |
| Gates-Swing-Entry | 2 | Each | \$ | 8,000.00 | \$ | 20,131 | 2005 | 25 | 2030 | 11 | No |
| Comments: Remove and replace. Cost and useful life page 2013: Repair/replace entrance gate hinge | • | | | | | | | | | | |
| Gates-Swing-Entry-Operators | 4 | Each | \$ | 2,500.00 | \$ | 10,211 | 2005 | 15 | 2020 | 1 | No |
| Comments: Cost and useful life provided by Metro Ov Remove and replace Elite high cycle swing | | Model CS | SW-2 | 00 operator | s wh | en they fail | | | | | |
| Landscape Renovation | 1 | Total | \$ | 5,000.00 | \$ | 5,213 | 2018 | 3 | 2021 | 2 | No |

Comments: Use this fund as needed for drainage correction and plant replacement; list year, work done and cost here. Budget cost provided by Yard n Garden.

2018: Installed new drainage completed by Valleyscapes \$3,491

2013: Replaced dead landscape shrub and trees by Yard n Garden \$3,600

| | Item Description | # of Items | Unit | | Current Item Cost | Re | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|------------------|---|-------------------|------------|------|-------------------------|------|---------------------------------------|---------------|----------------|-----------------|--------------|--------------|
| Lights-Exterior | | 1 | Total | \$ | 40,719.00 | \$ | 46,154 | 2005 | 20 | 2025 | 6 | No |
| Comments | : This component will serve as a budget f | und for replace | ment as r | eed | ed. Recomm | end | that the bo | ard ma | ke effor | ts to perf | orm wo | ork in |
| | lump sums in order to reduce varying us | seful life and co | ntractor i | nobi | ilization cost | s. A | lso, recomm | nend at | the tim | e of repla | cement | t board |
| | consult vendors to perform a fixture rep | olacement energ | gy audit. | | | | | | | | | |
| | 12 L2 walkway pole lamps @ \$904 | \$10,848 | | | | | | | | | | |
| | 8 L1 parking lot pole lamps @ \$1,263 | 10,104 | | | | | | | | | | |
| | 7 L3 wall pack lamps @ \$255 | 1,785 | | | | | | | | | | |
| | 60 breezeway can lamps @ \$150 | 9,000 | | | | | | | | | | |
| | 5 extra walkway pole lamps | 1,110 | | | | | | | | | | |
| | 3 oak tree spotlights @ \$356 | 1,068 | | | | | | | | | | |
| | extra entry wall packs | 510 | | | | | | | | | | |
| | Gate entry sign lighting | 548 | | | | | | | | | | |
| | 5 clubhouse lights @ \$292 | 1,460 | | | | | | | | | | |
| | 3 L2 walkway lights | 2,714 | | | | | | | | | | |
| | 5 site fixtures | 1,572 | | | | | | | | | | |
| Mailboxes | | 74 | Units | \$ | 140.00 | \$ | 14,469 | 2005 | 30 | 2035 | 16 | No |
| Comments | : 2005: Installed \$7,549 | | | | | | | | | | | |
| Paint-Exterior | | 75 | Units | \$ | 2,700.00 | \$ | 244,365 | 2018 | 10 | 2028 | 9 | No |
| Comments | : 2016: Board advised painting to be com | pleted as part o | of constru | ctio | n defect wor | k be | ing complet | ted 201 | L7 throu | gh 2019. | Moving | |
| | forward use 2018 as base year. Cost est | | | | | | | | | | | |
| | 2014: Manager advised that construction | | - | - | - | | · · · · · · · · · · · · · · · · · · · | | - | | | move |
| | Paint-Exterior to 2017. | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Paving-Asphalt-0 | Overlay | 68,500 | Sq.Ft. | \$ | 2.00 | \$ | 172,374 | 2005 | 25 | 2030 | 11 | No |

Comments: 2017: Completed by Pavement Maintenance \$9,900

Paving-Asphalt-Repair, Sealcoat & Restripe

2012: Completed by Sealskin LLC \$13,400

11 of 25

Sq.Ft. \$

0.20 \$

2017

14,586

2022

3

No

68,500

| Item Desc | Item Description # of Unit Item Replacen Items Cost Cost | | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? | | | | |
|---------------------------------|--|----------------|-----------------------------|---------------|----------------|-----------------|--------------|--------------|----|------|----|----|
| Pool-Cover-Loop Loc | | 1 | Total | \$ | 1,200.00 | \$ | 1,278 | 2007 | 15 | 2022 | 3 | No |
| Comments: Originally sche | duled for replacement in 2 | 018 | | | | | | | | | | |
| Pool-Deck-Resurface | | 1 | Total | \$ | 5,600.00 | \$ | 6,088 | 2013 | 10 | 2023 | 4 | No |
| Comments: 2013: Complet | ed by Key Property Service | s \$5,400 | | | | | | | | | | |
| Pool-Filter | | 1 | Total | \$ | 1,200.00 | \$ | 1,510 | 2015 | 15 | 2030 | 11 | No |
| Comments: Purex-Triton T | R-100 | | | | | | | | | | | |
| 2015: Replace | d, cost unknown. | | | | | | | | | | | |
| Pool-Furniture | | 1 | Total | \$ | 3,075.00 | \$ | 3,140 | 2015 | 5 | 2020 | 1 | No |
| Comments: 3 Tables-Meta | l (2015-Costco) | | | | | | | | | | | |
| 8 Chairs-Metal | (2015-Costco) | | | | | | | | | | | |
| 3 Umbrellas (2 | 015-Costco) | | | | | | | | | | | |
| Total | | \$2,650 | | | | | | | | | | |
| 7 Chairs-Vinyl- | Lounge (2006) @ \$50 | 350 | | | | | | | | | | |
| 3 Chairs (2006 |) @ \$25 | 75 | | | | | | | | | | |
| Pool-Heater | | 1 | Total | \$ | 3,200.00 | \$ | 3,268 | 2005 | 15 | 2020 | 1 | No |
| Comments: Purex-Triton N | IiniMax NT | | | | | | | | | | | |
| Pool-Pump-#1 | | 1 | Total | \$ | 1,100.00 | \$ | 1,300 | 2015 | 12 | 2027 | 8 | No |
| Comments: 2015: Replace | d by inhouse maintenance s | \$930 | | | | | | | | | | |
| Pool-Pump-#2 | | 1 | Total | \$ | 1,100.00 | \$ | 1,147 | 2009 | 12 | 2021 | 2 | No |
| Comments: Purex-Triton N | 1odel 38468400 | | | | | | | | | | | |
| Pool-Replaster & Tile Replaceme | ent | 728 | Sq.Ft. | \$ | 17.00 | \$ | 15,572 | 2018 | 12 | 2030 | 11 | No |
| Comments: Replaster 728 | sf | | | | | | | | | | | |
| 2018: Complet | ed by Pacific NW Pools \$12 | ,276 (\$17/sf |) | | | | | | | | | |
| 2017: Cost pro | vided by manager, based o | n bids solicit | ed \$12,000 |) | | | | | | | | |
| 2014: Manage | r advised to move replacem | nent year to 2 | 2016 | | | | | | | | | |
| Roof-Composition-Asphalt | | 680 | Squares | \$ | 450.00 | \$ | 385,010 | 2005 | 25 | 2030 | 11 | No |
| Roof-Gutters & Downspouts | | 2,811 | Ln.Ft. | \$ | 7.00 | ٠. | 27,482 | 2005 | 30 | 2035 | 16 | No |

Comments: 2016: Installation of leaf guards scheduled for completion. Cost unknown

12 of 25

| Item Description | # of Items | Unit | | Current Item Cost | Re | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|--|---------------|-------|----|-------------------------|----|-----------------------------|---------------|----------------|-----------------|--------------|--------------|
| Siding & Trim Repair | 74 | Units | \$ | 100.00 | \$ | 8,930 | 2018 | 10 | 2028 | 9 | No |
| Comments: Coordinate with Paint-Exterior. | | | | | | | | | | | |
| Siding-Inspection | 1 | Total | \$ | - | \$ | - | 2017 | 50 | 2067 | 48 | Yes |
| and provides the information needed to create deemed that a replacement of the siding (or be added to the reserve budget. 2017: Completed by Bear Consulting \$12,500 | portions o | - | _ | | | | • | | • | _ | |
| Sign-Entry-Clean & Repair | 1 | Total | \$ | - | \$ | - | 2015 | 50 | 2065 | 46 | Yes |
| Comments: Paid from Operating Budget | | | | | | | | | | | |
| Sign-Entry-Replace | 1 | Total | \$ | 6,000.00 | \$ | 6,801 | 2005 | 20 | 2025 | 6 | No |
| Signs-Building & Carport | 1 | Total | \$ | 3,000.00 | \$ | 3,620 | 2018 | 10 | 2028 | 9 | No |
| Comments: Remove and replace. | | | | | | | | | | | |
| Spa-Cover | 1 | Total | \$ | 800.00 | \$ | 852 | 2014 | 8 | 2022 | 3 | No |
| Comments: 2016: Cost and useful life provided by board | | | | | | | | | | | |
| Spa-Filter | 1 | Total | \$ | 1,200.00 | \$ | 1,251 | 2005 | 16 | 2021 | 2 | No |
| Comments: Purex-Triton TR-100 | | | | | | | | | | | |
| Spa-Heater | 1 | Total | \$ | 3,200.00 | \$ | 3,407 | 2010 | 12 | 2022 | 3 | No |
| Comments: Raypak C-R206A-EN-C. Installed by Char-el Po | ool & Spa. | | | | | | | | | | |
| Spa-Pumps | 2 | Each | \$ | 600.00 | \$ | 1,251 | 2009 | 12 | 2021 | 2 | No |
| Comments: Originally scheduled for completion in 2018 Purex-Triton Models 38468300 & 38468800 | | | | | | | | | | | |
| Spa-Replaster & Tile Replacement | 1 | Total | \$ | 1,200.00 | \$ | 1,479 | 2015 | 14 | 2029 | 10 | No |

Comments: Replaster 160

2015: Completed by Ad Tech NW \$1,200

2014: Manager advised to move replacement year to 2016

| | Item Description | # of Items | Unit | Current Item Cost | Re | Future placement Cost | Year Built | Useful Life | Year Replace | Life Left | One Time? |
|----------|------------------|---------------|-------|-------------------------|----|-----------------------------|---------------|----------------|-----------------|--------------|--------------|
| Treework | | 1 | Total | \$ 2,000.00 | \$ | 2,129 | 2019 | 3 | 2022 | 3 | No |

Comments: Have trees inspected by arborist and perform corrective pruning as needed to keep tree limbs at least 6' away from buildings. Tree limbs overhanging roofs and decks will damage and shorten the useful life of that component. Use this fund as needed over a 3 year period; list year, work done and cost here. Revise next cycle's budget according to arborist's recommendations.

2016: Scheduled for completion

2013: Tree pruning completed by Landscape Management \$2,600

Number of Items = 54

14 of 25

October 16, 2019

Funding Plan Summary

| Vintage | ()akc | Condoi | mınııım |
|----------|-------|---------|---------|
| VIIILUGE | Cuns | CUIIGUI | |

| tiober 16, 2019 | | rananig rian s | | | viiitage C | uks Condominic | |
|-----------------|-------------------|-------------------------------------|---------------------|------------------------|--------------------|------------------|---------------------------------------|
| Year | Percent Funded | Inflation Adjusted Ideal Balance | Starting Balance | Annual Contribution | Interest Income | Tax Liability | Inflation Adjusted Expenditures |
| 2020 | 37% | 647,760 | 240,760 | 89,000 | 29 | (9) | (66,005) |
| 2021 | 40% | 660,234 | 263,775 | 90,879 | 31 | (9) | (8,862) |
| 2022 | 47% | 730,051 | 345,813 | 92,798 | 39 | (12) | (31,726) |
| 2023 | 52 % | 777,707 | 406,913 | 94,758 | 45 | (14) | (12,828) |
| 2024 | 58% | 844,555 | 488,874 | 96,759 | 54 | (16) | (12,100) |
| 2025 | 63% | 912,391 | 573,571 | 98,802 | 62 | (19) | (70,107) |
| 2026 | 65% | 924,013 | 602,309 | 100,888 | 65 | (20) | (10,879) |
| 2027 | 70% | 995,106 | 692,363 | 103,018 | 74 | (22) | (26,945) |
| 2028 | 73 % | 1,050,726 | 768,488 | 105,193 | 82 | (25) | (269,948) |
| 2029 | 69% | 869,590 | 603,791 | 107,415 | 66 | (20) | (7,640) |
| 2030 | 74% | 950,941 | 703,612 | 109,683 | 76 | (23) | (615,703) |
| 2031 | 45% | 440,929 | 197,645 | 111,999 | 25 | (8) | (2,570) |
| 2032 | 56% | 544,106 | 307,092 | 114,364 | 36 | (11) | (29,648) |
| 2033 | 63 % | 620,851 | 391,833 | 116,779 | 45 | (14) | (25,585) |
| 2034 | 69% | 702,239 | 483,058 | 119,244 | 54 | (16) | (15,183) |
| 2035 | 74% | 794,365 | 587,157 | 121,762 | 65 | (19) | (274,557) |
| 2036 | 68% | 634,719 | 434,409 | 124,333 | 50 | (15) | (15,545) |
| 2037 | 74% | 734,418 | 543,232 | 126,959 | 61 | (18) | (30,726) |
| 2038 | 78 % | 819,619 | 639,507 | 129,640 | 70 | (21) | (330,847) |
| 2039 | 72 % | 612,360 | 438,349 | 132,377 | 50 | (15) | (16,853) |
| 2040 | 77% | 719,473 | 553,907 | 135,172 | 62 | (19) | (25,542) |
| 2041 | 81% | 818,469 | 663,581 | 138,026 | 73 | (22) | 0 |
| 2042 | 85% | 943,006 | 801,658 | 140,941 | 87 | (26) | (64,620) |
| 2043 | 87% | 1,004,370 | 878,040 | 143,917 | 95 | (28) | (24,759) |
| 2044 | 90% | 1,106,161 | 997,264 | 146,956 | 107 | (32) | (9,944) |
| 2045 | 93% | 1,222,978 | 1,134,351 | 150,059 | 121 | (36) | (117,632) |
| 2046 | 94% | 1,235,086 | 1,166,862 | 153,227 | 124 | (37) | (20,912) |
| 2047 | 97% | 1,344,377 | 1,299,265 | 156,463 | 138 | (41) | (29,966) |
| 2048 | 99% | 1,445,273 | 1,425,858 | 159,767 | 151 | (45) | (415,367) |
| 2049 | 100% | 1,170,372 | 1,170,364 | 140,684 | 124 | (37) | (13,096) |
| | | | Total | \$3,651,860 | \$2,163 | (\$649) | (\$2,596,096) |
| | | | | | | | |

| 0.01% | Investment Rate |
|--------|-----------------|
| 30.00% | Tax Rate |
| 2.11% | Inflation Rate |
| 0.00% | State Tax |

Weak (0-35%)

Fair (36-70%)

Strong (71-100%)

October 16, 2019

Fully Funded at 30 Years Funding Plan Summary

Vintage Oaks Condominium

| Year | Percent Funded | Inflation Adjusted Ideal Balance | Starting Balance | Annual Contribution | Interest Income | Tax Liability | Inflation Adjusted Expenditures |
|------|-------------------|-------------------------------------|---------------------|------------------------|--------------------|------------------|---------------------------------------|
| 2020 | 37% | 647,760 | 240,760 | 89,000 | 29 | (9) | (66,005) |
| 2021 | 40% | 660,234 | 263,775 | 90,879 | 31 | (9) | (8,862) |
| 2022 | 47% | 730,051 | 345,813 | 92,798 | 39 | (12) | (31,726) |
| 2023 | 52% | 777,707 | 406,913 | 94,758 | 45 | (14) | (12,828) |
| 2024 | 58% | 844,555 | 488,874 | 96,759 | 54 | (16) | (12,100) |
| 2025 | 63% | 912,391 | 573,571 | 98,802 | 62 | (19) | (70,107) |
| 2026 | 65% | 924,013 | 602,309 | 100,888 | 65 | (20) | (10,879) |
| 2027 | 70% | 995,106 | 692,363 | 103,018 | 74 | (22) | (26,945) |
| 2028 | 73 % | 1,050,726 | 768,488 | 105,193 | 82 | (25) | (269,948) |
| 2029 | 69% | 869,590 | 603,791 | 107,415 | 66 | (20) | (7,640) |
| 2030 | 74% | 950,941 | 703,612 | 109,683 | 76 | (23) | (615,703) |
| 2031 | 45% | 440,929 | 197,645 | 111,999 | 25 | (8) | (2,570) |
| 2032 | 56% | 544,106 | 307,092 | 114,364 | 36 | (11) | (29,648) |
| 2033 | 63 % | 620,851 | 391,833 | 116,779 | 45 | (14) | (25,585) |
| 2034 | 69% | 702,239 | 483,058 | 119,244 | 54 | (16) | (15,183) |
| 2035 | 74% | 794,365 | 587,157 | 121,762 | 65 | (19) | (274,557) |
| 2036 | 68% | 634,719 | 434,409 | 124,333 | 50 | (15) | (15,545) |
| 2037 | 74% | 734,418 | 543,232 | 126,959 | 61 | (18) | (30,726) |
| 2038 | 78% | 819,619 | 639,507 | 129,640 | 70 | (21) | (330,847) |
| 2039 | 72 % | 612,360 | 438,349 | 132,377 | 50 | (15) | (16,853) |
| 2040 | 77% | 719,473 | 553,907 | 135,172 | 62 | (19) | (25,542) |
| 2041 | 81% | 818,469 | 663,581 | 138,026 | 73 | (22) | 0 |
| 2042 | 85 % | 943,006 | 801,658 | 140,941 | 87 | (26) | (64,620) |
| 2043 | 87% | 1,004,370 | 878,040 | 143,917 | 95 | (28) | (24,759) |
| 2044 | 90% | 1,106,161 | 997,264 | 146,956 | 107 | (32) | (9,944) |
| 2045 | 93% | 1,222,978 | 1,134,351 | 150,059 | 121 | (36) | (117,632) |
| 2046 | 94% | 1,235,086 | 1,166,862 | 153,227 | 124 | (37) | (20,912) |
| 2047 | 97% | 1,344,377 | 1,299,265 | 156,463 | 138 | (41) | (29,966) |
| 2048 | 99% | 1,445,273 | 1,425,858 | 159,767 | 151 | (45) | (415,367) |
| 2049 | 100% | 1,170,372 | 1,170,364 | 140,684 | 124 | (37) | (13,096) |
| | | | Total | \$3,651,860 | \$2,163 | (\$649) | (\$2,596,096 |

0.01% Investment Rate 30.00% Tax Rate 2.11% Inflation Rate 0.00% State Tax

Weak (0-35%) Fair (36-70%) Strong (71-100%)

Baseline Funding Plan Summa

| October 16, 2019 | Funding Plan Summary | Vintage Oaks Condominium |
|------------------|----------------------|--------------------------|
|------------------|----------------------|--------------------------|

| Year | Percent Funded | Inflation Adjusted Ideal Balance | Starting Balance | Annual Contribution | Interest Income | Tax Liability | Inflation Adjusted Expenditures | |
|------|-------------------|-------------------------------------|---------------------|------------------------|--------------------|------------------|---------------------------------------|--|
| 2020 | 37% | 647,760 | 240,760 | 85,381 | 28 | (9) | (66,005) | |
| 2021 | 39% | 660,234 | 260,156 | 85,381 | 30 | (9) | (8,862) | |
| 2022 | 46% | 730,051 | 336,696 | 85,381 | 38 | (11) | (31,726) | |
| 2023 | 50% | 777,707 | 390,378 | 85,381 | 43 | (13) | (12,828) | |
| 2024 | 55% | 844,555 | 462,961 | 85,381 | 51 | (15) | (12,100) | |
| 2025 | 59% | 912,391 | 536,279 | 85,381 | 58 | (17) | (70,107) | |
| 2026 | 60% | 924,013 | 551,593 | 85,381 | 59 | (18) | (10,879) | |
| 2027 | 63% | 995,106 | 626,137 | 85,381 | 67 | (20) | (26,945) | |
| 2028 | 65% | 1,050,726 | 684,619 | 85,381 | 73 | (22) | (269,948) | |
| 2029 | 58% | 869,590 | 500,103 | 85,381 | 54 | (16) | (7,640) | |
| 2030 | 61% | 950,941 | 577,883 | 85,381 | 62 | (19) | (615,703) | |
| 2031 | 11% | 440,929 | 47,604 | 85,381 | 9 | (3) | (2,570) | |
| 2032 | 24% | 544,106 | 130,423 | 85,381 | 17 | (5) | (29,648) | |
| 2033 | 30% | 620,851 | 186,168 | 85,381 | 23 | (7) | (25,585) | |
| 2034 | 35% | 702,239 | 245,980 | 85,381 | 29 | (9) | (15,183) | |
| 2035 | 40% | 794,365 | 316,199 | 85,381 | 36 | (11) | (274,557) | |
| 2036 | 20% | 634,719 | 127,049 | 85,381 | 17 | (5) | (15,545) | |
| 2037 | 27% | 734,418 | 196,897 | 85,381 | 24 | (7) | (30,726) | |
| 2038 | 31% | 819,619 | 251,569 | 85,381 | 29 | (9) | (330,847) | |
| 2039 | 1% | 612,360 | 6,124 | 85,381 | 5 | (1) | (16,853) | |
| 2040 | 10% | 719,473 | 74,655 | 85,381 | 12 | (4) | (25,542) | |
| 2041 | 16% | 818,469 | 134,502 | 85,381 | 18 | (5) | 0 | |
| 2042 | 23% | 943,006 | 219,896 | 85,381 | 26 | (8) | (64,620) | |
| 2043 | 24% | 1,004,370 | 240,675 | 85,381 | 28 | (9) | (24,759) | |
| 2044 | 27% | 1,106,161 | 301,317 | 85,381 | 34 | (10) | (9,944) | |
| 2045 | 31% | 1,222,978 | 376,779 | 85,381 | 42 | (13) | (117,632) | |
| 2046 | 28% | 1,235,086 | 344,557 | 85,381 | 39 | (12) | (20,912) | |
| 2047 | 30% | 1,344,377 | 409,054 | 85,381 | 45 | (14) | (29,966) | |
| 2048 | 32% | 1,445,273 | 464,501 | 85,381 | 51 | (15) | (415,367) | |
| 2049 | 11% | 1,170,372 | 134,551 | 85,381 | 18 | (5) | (13,096) | |

Total \$2,561,439 \$1,066 (\$320) (\$2,596,096)

0.01%Investment Rate30.00%Tax Rate2.11%Inflation Rate0.00%State Tax

| Octo | her | 16 | 2019 |
|------|-----|----|------|

Annual Expenditures

Vintage Oaks Condominium

| Year | Amount | Item Description |
|------|--------|--|
| | 6,024 | Barkdust |
| | 5,616 | Clubhouse-Air Conditioning Unit |
| | 2,297 | Clubhouse-Appliances |
| | 5,122 | Clubhouse-Flooring-Carpet |
| | 7,658 | Clubhouse-Furnace |
| | 12,764 | Clubhouse-Furniture |
| | 919 | Clubhouse-Hot Water Heater |
| | 3,063 | Gate-Access System-Loops |
| | 3,880 | Gate-Access System Gate-Entry Access System |
| | 2,042 | Gate-Entry Access System Gate-Sensors |
| | | |
| | 10,211 | Gates-Swing-Entry-Operators Pool-Furniture |
| | 3,140 | |
| | 3,268 | Pool-Heater |
| 2020 | 66,005 | |
| | 5,213 | Landscape Renovation |
| | 1,147 | Pool-Pump-#2 |
| | 1,251 | Spa-Filter |
| | 1,251 | Spa-Pumps |
| | , - | The state of the s |
| 2021 | 8,862 | |
| | 6,281 | Barkdust |
| | 3,194 | Concrete Safety Repair |
| | 14,586 | Paving-Asphalt-Repair, Sealcoat & Restripe |
| | 1,278 | Pool-Cover-Loop Loc |
| | 852 | Spa-Cover |
| | 3,407 | Spa-Heater |
| | 2,129 | Treework |
| 2022 | 31,726 | |
| | 3,587 | Clubhouse-Exercise Equipment |
| | 3,153 | Clubhouse-Office Equipment |
| | 6,088 | Pool-Deck-Resurface |
| 2023 | 12,828 | |
| | 6,549 | Barkdust |
| | 5,550 | Landscape Renovation |
| 2024 | 12,100 | |
| | | |

| Year | Amount | Item Description |
|------|---------|--|
| | 3,400 | Clubhouse-Bathrooms-Renovation |
| | 907 | Clubhouse-Drinking Fountain |
| | 2,956 | Clubhouse-Flooring-Tile |
| | 2,777 | Clubhouse-Lights |
| | 510 | Clubhouse-Window Treatments |
| | 850 | Garage Door-Maintenance |
| | 46,154 | Lights-Exterior |
| | 3,485 | Pool-Furniture |
| | 6,801 | Sign-Entry-Replace |
| | 2,267 | Treework |
| 2025 | 70,107 | |
| | 6,829 | Barkdust |
| | 4,051 | Clubhouse-Paint-Interior |
| 2026 | 10,879 | |
| | 3,545 | Concrete Safety Repair |
| | 5,909 | Landscape Renovation |
| | 16,191 | Paving-Asphalt-Repair, Sealcoat & Restripe |
| _ | 1,300 | Pool-Pump-#1 |
| 2027 | 26,945 | |
| | 7,120 | Barkdust |
| | 3,500 | Clubhouse-Office Equipment |
| | 244,365 | Paint-Exterior |
| | 8,930 | Siding & Trim Repair |
| | 3,620 | Signs-Building & Carport |
| _ | 2,413 | Treework |
| 2028 | 269,948 | |
| | 3,573 | Clubhouse-Keyless Access System |
| | 2,588 | Clubhouse-Security Camera |
| | 1,479 | Spa-Replaster & Tile Replacement |
| 2029 | 7,640 | |
| | 7,423 | Barkdust |
| | 2,516 | Gate-Sensors |
| | 20,131 | Gates-Swing-Entry |
| | 6,291 | Landscape Renovation |
| | 172,374 | Paving-Asphalt-Overlay |
| | 1,510 | Pool-Filter |
| | 3,869 | Pool-Furniture |
| | 15,572 | Pool-Replaster & Tile Replacement |
| | 385,010 | Roof-Composition-Asphalt |
| | | |

| Year | Amount | Item Description |
|------|------------------|---|
| | 1,007 | Spa-Cover |
| 2030 | 615,703 | |
| | 2,570 | Treework |
| 2031 | 2,570 | |
| | 7,740 | Barkdust |
| | 3,936 17,972 | Concrete Safety Repair Paving-Asphalt-Repair, Sealcoat & Restripe |
| 2032 | 29,648 | |
| | 4,420 | Clubhouse-Exercise Equipment |
| | 3,885 | Clubhouse-Office Equipment |
| | 6,698 7,501 | Landscape Renovation Pool-Deck-Resurface |
| | 1,473 | Pool-Pump-#2 |
| | 1,607 | Spa-Pumps |
| 2033 | 25,585 | |
| | 8,070 | Barkdust |
| | 4,377 | Spa-Heater |
| | 2,736 | Treework |
| 2034 | 15,183 | |
| | 7,682 | Clubhouse-Air Conditioning Unit |
| | 3,142 | Clubhouse-Appliances Clubhouse-Flooring-Carpet |
| | 7,006 10,475 | Clubhouse-Furnace |
| | 17,458 | Clubhouse-Furniture |
| | 1,257 | Clubhouse-Hot Water Heater |
| | 153,357 | Fence-Perimeter-Chainlink-Vinyl-6' |
| | 4,190 | Gate-Access System-Loops |
| | 5,307 | Gate-Entry Access System |
| | 13,967 14,469 | Gates-Swing-Entry-Operators Mailboxes |
| | 4,295 | Pool-Furniture |
| | 4,469 | Pool-Heater |
| | 27,482 | Roof-Gutters & Downspouts |
| 2035 | 274,557 | |
| | 8,414 | Barkdust |
| | 7,131 | Landscape Renovation |

| Year | Amount | Item Description |
|------|---|---|
| 2036 | 15,545 | |
| | 4,369 19,950 1,747 1,747 2,912 | Concrete Safety Repair Paving-Asphalt-Repair, Sealcoat & Restripe Pool-Cover-Loop Loc Spa-Filter Treework |
| 2037 | 30,726 | |
| | 8,773 4,312 301,108 11,003 4,461 1,190 | Barkdust Clubhouse-Office Equipment Paint-Exterior Siding & Trim Repair Signs-Building & Carport Spa-Cover |
| 2038 | 330,847 | |
| 2039 | 4,403 3,188 7,592 1,670 16,853 | Clubhouse-Keyless Access System Clubhouse-Security Camera Landscape Renovation Pool-Pump-#1 |
| | 9,147 5,426 3,101 4,767 3,101 | Barkdust Clubhouse-Paint-Interior Gate-Sensors Pool-Furniture Treework |
| 2040 | 25,542 | |
| | 9,537 4,849 8,082 22,146 20,006 | Barkdust Concrete Safety Repair Landscape Renovation Paving-Asphalt-Repair, Sealcoat & Restripe Pool-Replaster & Tile Replacement |
| 2042 | 64,620 | |
| | 5,447 4,787 9,243 1,981 3,301 | Clubhouse-Exercise Equipment Clubhouse-Office Equipment Pool-Deck-Resurface Spa-Replaster & Tile Replacement Treework |

| October 16, 2019 | Annual Expenditures | | Vintage Oaks Condominium |
|------------------|---------------------|------------------|--------------------------|
| Year | Amount | Item Description | |
| 2043 | 24,759 | | |
| | 9,944 | Barkdust | |

| | Amount | item bescription |
|------|----------------|---|
| 2043 | 24,759 | |
| | 9,944 | Barkdust |
| 2044 | 9,944 | |
| | F 162 | Chilebrane Batharana Bananatian |
| | 5,163 | Clubhouse-Bathrooms-Renovation |
| | 1,377 | Clubhouse-Drinking Fountain |
| | 4,488 | Clubhouse-Flooring-Tile |
| | 4,216 | Clubhouse-Lights |
| | 774 | Clubhouse-Window Treatments |
| | 1,291 | Garage Door-Maintenance |
| | 8,605 | Landscape Renovation |
| | 70,076 | Lights-Exterior |
| | 2,065 | Pool-Filter |
| | 5,292 | Pool-Furniture |
| | 1,893 | Pool-Pump-#2 |
| | 10,326 | Sign-Entry-Replace |
| | 2,065 | Spa-Pumps |
| 2045 | 117,632 | |
| | 10,368 | Barkdust |
| | 1,406 | Spa-Cover |
| | 5,623 | Spa-Heater |
| | 3,515 | Treework |
| | | |
| 2046 | 20,912 | |
| | 5,383 | Concrete Safety Repair |
| | 24,583 | Paving-Asphalt-Repair, Sealcoat & Restripe |
| 2047 | 29,966 | |
| | 10,810 | Barkdust |
| | 5,313 | Clubhouse-Office Equipment |
| | 9,161 | Landscape Renovation |
| | 371,027 | Paint-Exterior |
| | 13,559 | Siding & Trim Repair |
| | 5,497 | Signs-Building & Carport |
| 2048 | 415,367 | |
| | 5,426 | Clubbouse-Keyless Access System |
| | 3,426 3,929 | Clubhouse-Keyless Access System Clubhouse-Security Camera |
| | 3,929 3,742 | Treework |
| 2049 | 13,096 | |

| October 16, 2019 Annual Expenditures | | | Vintage Oaks Condominium |
|--------------------------------------|-----------|------------------|--------------------------|
| Year | Amount | Item Description | |
| Total | 2,596,096 | | |

| Item Description | Useful Life | Life Left | Year Replace | Re | Future placement Cost | Ideal Balance | | Actual Balance |
|--|----------------|--------------|-----------------|----|-----------------------------|------------------|----|-------------------|
| Barkdust | 2 | 1 | 2020 | \$ | 6,024 | \$ 6,024 | \$ | 6,024 |
| Clubhouse-Air Conditioning Unit | 15 | 1 | 2020 | \$ | 5,616 | \$ 5,616 | \$ | 5,616 |
| Clubhouse-Appliances | 15 | 1 | 2020 | \$ | 2,297 | \$ 2,297 | \$ | 2,297 |
| Clubhouse-Bathrooms-Renovation | 20 | 6 | 2025 | \$ | 3,400 | \$ 2,550 | \$ | 2,550 |
| Clubhouse-Drinking Fountain | 20 | 6 | 2025 | \$ | 907 | \$ 680 | \$ | 680 |
| Clubhouse-Exercise Equipment | 10 | 4 | 2023 | \$ | 3,587 | \$ 2,511 | \$ | 2,511 |
| Clubhouse-Flooring-Carpet | 15 | 1 | 2020 | \$ | 5,122 | \$ 5,122 | \$ | 5,122 |
| Clubhouse-Flooring-Tile | 20 | 6 | 2025 | \$ | 2,956 | \$ 2,217 | \$ | 2,217 |
| Clubhouse-Furnace | 15 | 1 | 2020 | \$ | 7,658 | \$ 7,658 | \$ | 7,658 |
| Clubhouse-Furniture | 15 | 1 | 2020 | \$ | 12,764 | \$ 12,764 | \$ | 12,764 |
| Clubhouse-Hot Water Heater | 15 | 1 | 2020 | \$ | 919 | \$ 919 | \$ | 919 |
| Clubhouse-Keyless Access System | 10 | 10 | 2029 | \$ | 3,573 | \$ 357 | \$ | 357 |
| Clubhouse-Lights | 20 | 6 | 2025 | \$ | 2,777 | \$ 2,083 | \$ | 2,083 |
| Clubhouse-Office Equipment | 5 | 4 | 2023 | \$ | 3,153 | \$ 1,261 | \$ | 1,261 |
| Clubhouse-Paint-Interior | 14 | 7 | 2026 | \$ | 4,051 | \$ 2,315 | \$ | 2,315 |
| Clubhouse-Security Camera | 10 | 10 | 2029 | \$ | 2,588 | \$ 259 | \$ | 259 |
| Clubhouse-Window Treatments | 20 | 6 | 2025 | \$ | 510 | \$ 383 | \$ | 383 |
| Concrete Safety Repair | 5 | 3 | 2022 | \$ | 3,194 | \$ 1,916 | \$ | 1,916 |
| Construction Defect Repair-Phase 1 | 50 | 48 | 2067 | \$ | - | \$ - | \$ | - |
| Dumpster Enclosures-Clean & Repair | 50 | 47 | 2066 | \$ | - | \$ - | \$ | - |
| Fence-Perimeter-Chainlink-Vinyl-6' | 30 | 16 | 2035 | \$ | 153,357 | \$ 76,678 | \$ | - |
| Garage Door-Maintenance | 20 | 6 | 2025 | \$ | 850 | \$ 638 | \$ | 638 |
| Gate-Access System-Loops | 15 | 1 | 2020 | \$ | 3,063 | \$ 3,063 | \$ | 3,063 |
| Gate-Entry Access System | 15 | 1 | 2020 | \$ | 3,880 | \$ 3,880 | \$ | 3,880 |
| Gate-Sensors | 10 | 1 | 2020 | \$ | 2,042 | \$ 2,042 | \$ | 2,042 |
| Gates-Swing-Entry | 25 | 11 | 2030 | \$ | 20,131 | \$ 12,079 | \$ | 12,079 |
| Gates-Swing-Entry-Operators | 15 | 1 | 2020 | \$ | 10,211 | \$ 10,211 | \$ | 10,211 |
| Landscape Renovation | 3 | 2 | 2021 | \$ | 5,213 | \$ 3,475 | \$ | 3,475 |
| Lights-Exterior | 20 | 6 | 2025 | \$ | 46,154 | \$ 34,615 | \$ | 34,615 |
| Mailboxes | 30 | 16 | 2035 | \$ | 14,469 | \$ 7,235 | \$ | - |
| Paint-Exterior | 10 | 9 | 2028 | \$ | 244,365 | \$ 48,873 | | 48,873 |
| Paving-Asphalt-Overlay | 25 | 11 | 2030 | \$ | 172,374 | \$ 103,424 | \$ | 25,085 |
| Paving-Asphalt-Repair, Sealcoat & Restripe | 5 | 3 | 2022 | \$ | 14,586 | \$ 8,751 | \$ | 8,751 |
| Pool-Cover-Loop Loc | 15 | 3 | 2022 | \$ | 1,278 | \$ 1,107 | \$ | 1,107 |
| Pool-Deck-Resurface | 10 | 4 | 2023 | \$ | 6,088 | \$ 4,261 | \$ | 4,261 |
| Pool-Filter | 15 | 11 | 2030 | \$ | 1,510 | \$ 503 | \$ | 503 |
| Pool-Furniture | 5 | 1 | 2020 | \$ | 3,140 | \$ 3,140 | \$ | 3,140 |
| Pool-Heater | 15 | 1 | 2020 | \$ | 3,268 | \$ 3,268 | \$ | 3,268 |
| Pool-Pump-#1 | 12 | 8 | 2027 | \$ | 1,300 | \$ 542 | \$ | 542 |
| Pool-Pump-#2 | 12 | 2 | 2021 | \$ | 1,147 | \$ 1,051 | \$ | 1,051 |
| Pool-Replaster & Tile Replacement | 12 | 11 | 2030 | \$ | 15,572 | \$ 2,595 | \$ | 2,595 |
| Roof-Composition-Asphalt | 25 | 11 | 2030 | \$ | 385,010 | \$ 231,006 | _ | -,555 |
| Roof-Gutters & Downspouts | 30 | 16 | 2035 | \$ | 27,482 | \$ 13,741 | • | _ |
| Siding & Trim Repair | 10 | 9 | 2028 | \$ | 8,930 | \$ 1,786 | \$ | 1,786 |

| Item Description | Useful Life | Life Left | Year Replace | Re | Future eplacement Cost | Ideal Balance | Actual Balance |
|----------------------------------|----------------|--------------|-----------------|----|------------------------------|------------------|-------------------|
| Siding-Inspection | 50 | 48 | 2067 | \$ | - | \$ - | \$ - |
| Sign-Entry-Clean & Repair | 50 | 46 | 2065 | \$ | - | \$ - | \$ - |
| Sign-Entry-Replace | 20 | 6 | 2025 | \$ | 6,801 | \$ 5,101 | \$ 5,101 |
| Signs-Building & Carport | 10 | 9 | 2028 | \$ | 3,620 | \$ 724 | \$ 724 |
| Spa-Cover | 8 | 3 | 2022 | \$ | 852 | \$ 639 | \$ 639 |
| Spa-Filter | 16 | 2 | 2021 | \$ | 1,251 | \$ 1,173 | \$ 1,173 |
| Spa-Heater | 12 | 3 | 2022 | \$ | 3,407 | \$ 2,839 | \$ 2,839 |
| Spa-Pumps | 12 | 2 | 2021 | \$ | 1,251 | \$ 1,147 | \$ 1,147 |
| Spa-Replaster & Tile Replacement | 14 | 10 | 2029 | \$ | 1,479 | \$ 528 | \$ 528 |
| Treework | 3 | 3 | 2022 | \$ | 2,129 | \$ 710 | \$ 710 |
| | | | | \$ | 1,237,306 | \$ 647,760 | \$ 240,760 |

Investment Rate 0.01%

Tax Rate 30.00%

Inflation Rate 2.11% Contingency Rate 0.00%

Contingency \$ - \$
Total \$ 647,760 \$ 240,760